

Taos Operations & Maintenance Facility Update

NCRTD Executive Board of Directors Meeting

December 8, 2023

Blue
bus

NORTH
CENTRAL
RTD

RidetheBlueBus.com
505-629-4725
866-206-0754



Aerial Views



Aerial Views



Aerial Views



Aerial Views



Aerial Views



Aerial Views



Aerial Views



Aerial Views



Construction Highlights

View of Site Looking SE From The NW



View of Site Looking North From Entrance off of Salazar



Construction Highlights

Concrete Stem Walls with Fresh Concrete Placement / Rebar



Concrete Stem Walls with Fresh Concrete Placement / Rebar



Construction Highlights

**Masonry Stem Wall and Burnished Block /
Rebar / Electrical Conduit**



**Masonry Stem Wall / Vertical and Horizontal
Rebar / Electrical Conduit**



Construction Highlights

Taking Soil Density Tests at Masonry Retaining Wall Trench



View of Site Looking NW From North Center of Site with Fueling Station





Thank you!
Questions?

RidetheBlueBus.com
505-629-4725
866-206-0754